

On-car analysis list from May 30th, 2023
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Tiguan	21-23	All	All	MIL-on P0442	Customer states MIL-on, fault P0442 stored in ECM memory (Untouched vehicle)
	Atlas, Atlas Cross Sport	23	3.6L CDVC	All	MIL-on P0322	Customer states MIL-on, P0322 stored in ECM memory (Untouched vehicle)
	Atlas, Atlas Cross Sport	23	3.6L CDVC	All	MIL-on P0461	Customer states MIL-on, fault P0461 stored in ECM memory (Attach MVBs IDE03472 and IDE03473 from Address 17 to GFF log)
Chassis	Tiguan, Taos	22-23	All	All	Front Drive Shaft Noise	Noise from front end while driving (popping, grinding, knocking, swishing, clicking, thumping and/or creaking noise)
Electric	ID.4	23	All	All	Taillight Condensation	Customer states condensation in the taillights (Untouched vehicle)
	Tiguan	22-20	All	All	Seat Fault B201000, B135354 and/or B135454	Customer states seat memory is inoperative (Must have B201000, B135354 and/or B135454 in address 36) (Untouched vehicle)
	Atlas, Cross Sport, Jetta, Taos, Tiguan	22-23	All	All	Key Battery	Customer states key FOB lock/unlock functions do not work via button press (not KESSY). (Must have B147918 and/or B147A18 in Address 09)
	ID.4	23	All	All	Seat Fault B135554	Customer states seat memory is inoperative (Must have B135554 in address 36) (Untouched vehicle)
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract