



Preliminary Information

PIC6496A MIL DTC P30EF

Proactive
Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2022 - 2023	All	All	2.0L (LSY)	All
Cadillac	CT5	2022 - 2023	All	All	2.0L (LSY)	All
Chevrolet	Blazer	2023	All	All	2.0L (LSY)	All
GMC	Acadia	2023	All	All	2.0L (LSY)	All

Involved Region or Country	North America
Condition	Some Customers may see MIL illuminated and technicians may find DTC P30EF set in the ECM.
Cause	Hardware anomaly in cooling fan motor

Correction:

Currently engineering is working on a fix and this PI will be updated with the solution.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0542309	Engine Malfunction Indicator Lamp (MIL) Active - Customer Concern Not Duplicated (CCND)	0.3 Hr.*
*You may claim up to the allowable labor hours		

Version History

Version	2
Modified	03/10/2023 - Created on. 05/11/2023 - updated to additional models



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.