



Bulletin No.: PIC6507
Published date: 05/25/2023

Preliminary Information

PIC6507 Service Vehicle Soon U164E Setting In BECM

[Proactive](#)
[Models](#)

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD
Condition	Some customers may notice the SVS (Service Vehicle Soon) message. Technicians may see U164E setting in the BECM (Battery Energy Control Module)
Cause	BECM Software Anomaly

Correction:

If the vehicle returns to the dealership for this concern, the SVS light will likely not be illuminated and the DTC U164E will be in history that caused this.

Do not attempt any repairs or replace any parts at this time.

Engineering is aware of this concern and working on a resolution.

This PI will be updated when the resolution is available.

Version History

Version	1
Modified	05/24/2023 - Created.

