



Technical Service Bulletin

01 PSS MIL on P060C00, P060600, P0A0F00 Drive System: Fault Stored in the ECM

01 23 71 2071203/1 August 23, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2019 – 2021	All	2.0L engine

Condition

This bulletin applies to 2019 – 2021 A6 with 2.0L engine only.

Customer states:

- “Drive system: fault” is displayed in the driver information system.
- MIL on.

Workshop findings:

The following DTC is stored in the ECM, J623 (address word 0001):

- **P060600** – “Engine control module faulty” with Symptom code 15139.
- **P060C00** – “Engine control module internal system failure” with Symptom code 30794 and/or 37379.
- **P0A0F00** – “Engine does not start” with Symptom code 38653.

Technical Background

Under analysis.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. If the customer’s vehicle condition matches the findings listed in the *Condition* section of this PSS TSB, clear the DTCs and return the vehicle to the customer. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2023 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer’s concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2071203**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2023 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.