



Technical Service Bulletin

19 Red coolant warning lamp comes on OR MIL on, DTC P218100 and/or P1BB400

19 23 42 2069248/4 September 7, 2023. Supersedes Technical Service Bulletin Group 19 number 23-40 dated August 10, 2023, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019 – 2021	All	4.0 engine
S8, SQ7, SQ8, and RS Q8	2020 – 2022		Not Applicable
RS 6 Avant, and RS 7	2021 – 2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Condition</i> (Updated workshop findings)
3	08/10/2023	Revised <i>Service</i> (Updated service instructions)
2	5/10/2023	Revised <i>Service</i> (Updated service instructions)

Customer states:

- The red coolant temperature warning is displayed in the instrument cluster and the engine fans are running. However, according to the coolant temperature gauge, the engine temperature is not excessively high.

Or

- MIL on.

Workshop findings:

The following DTCs are stored in the Engine Control Module, -J623- (address word 0001):

- DTC P218100:** Cooling System Performance. **(Must be stored.)**
- DTC P1BB400:** Cylinder head temperature too low. **(May also be present)**



Note: If DTCs **P017B00**, **P017C00** or **P017E00** are also stored in the ECM, please refer to TSB 2062951.

Technical Background

In some instances, corrosion between the brass bushing and the heating pin leads to inaccurate open and close positions during the operating temperature range. The surface treatment process of the thermostat sleeve has been improved to minimize corrosion.



Technical Service Bulletin

Production Solution

Not applicable.

Service

Replace Map Controlled Engine Cooling Thermostat F265.

Please also check that the ball-type non-return valves in the two quick-release couplings for the coolant breather line which connects the engine and the main radiator to the coolant expansion tank are present and are working correctly. To ensure correct functioning, the balls must be able to move freely and the valves must open in the normal direction of flow toward the expansion tank but close toward the engine/main radiator (refer to “Connection diagram – coolant lines” in ELSA).

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only		
Service Number:	1958		
Damage Code:	0010		
	Thermostat remove + reinstall	1958 1973	See SRT with associated operations.
	Check non-return valves	1986 2099	20 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 15 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2069248/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10).

Additional Information

All part and service references provided in this TSB (**2069248**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.