

Audi On-car analysis list from October, 1 2023

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [ServiceNet>>Technician References>>Vin-4-Pin>>Worksheets](#)

	Models	MY	Engine	Trans	Topic	Topic details
PT	Q3	2020-2021	All	All	Coolant warning Lamp	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir - Case does not relate to TSB 2061918 - Photo showing reservoir level
	A6, A7, Q7, Q8, S4, S5	2019-2023	3.0L	All	Catalytic Converter Inspection , P042000: Catalyst System,Bank1 Efficiency Below	- GFF Log with all fault codes and completed test plans. - Oil and Fuel samples (Hazmat containers can be requested through TAC). After oil sample have been collected, oil and filter should be changed. - VIN-4-Pin Worksheet with answers to questions
	All models with 3.0L engine (EA839)	2021-2023	3.0L (EA839)	All	Abnormal/no sound from engine sound generator	- Video/ sound recording of abnormal noise/ customer complaint from inside the vehicle before repair. - Video/ sound recording while running sound actuator test - Upload GFF log with executed test and relevant DTCs to GFF paperless - Video/ sound record of noise from inside the vehicle after repair.
	A4	2023	All	All	Coolant leak from expansion tank	Photo documentation of the source of the leak
	Q3	2019-2023	All	All	P008700 Low fuel pressure	Applies to Q3 models within NVLW only - DTC P008700 - Attach completed worksheet on initial TAC contact.
	A6, A7, Q7, Q8, S4, S5	2020-2024	EA839 3.0L 2.9L	All	Parts Block Belt tension damper 06M903133AA	Only applicable if no prior repairs to Starter generator/ belt drive system performed. See worksheet
	Q4 e-tron	2022-2024	All	All	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	e-tron Q and SB Q8 e-tron and SB	2019-2024	All	All	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	Q3	2020-2023	All	All	Q3 oil pan leak	Oil leak found coming from the oil pan.
EL	e-tron GT	2022-2024	All	All	Corrosion found in door module	Customer concern that a door module function is inoperative Upon inspection corrosion is found on door module pins Photo document findings, water test, inspect door harness and pillar connection
	SQ5	2018-2024	All	All	Wire broke at air compressor V66	DTC P089200 Broken/Damaged/Loose connection found at V66 (Suspension Compressor) T3DL
BD	e-tron Quattro e-tron SB	2021-2022	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving - Video of noise before repair is performed - Photos of repair
	A5	2021-2022	Any	Any	Noise from Front Door speaker Grill	Noise from front door trim panel while driving - Video of noise before repair is performed - Photos of repair