

Technical product information

Topic	Bentley dynamic ride system warning displayed - DTC P0B2600 with symptom code 28672
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2065922/3
Level	EH
Status	Released for publishing
Release date	03-Oct-2023

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0021 - Battery management 2	P0B2600: Hybrid/EV Battery "A" Voltage High		Intermittent
0021 - Battery management 2	P0B2600: Hybrid/EV Battery "A" Voltage High		static

New customer code

Object of complaint	Complaint type	Position
running gear -> shock absorber/suspension control -> roll compensation	functionality -> defective function sequence	
lighting system, signalling -> sound signals -> accoustic warning for shock absorber/suspension control	functionality -> warning signal sounds without reason	
information, navigation, communication, entertainment -> symbolic control indicators -> warning lamp for electronic stabilisation programme (ESC)	functionality -> activates without reason	
information, navigation, communication, entertainment -> symbolic information indicators -> anti-roll bar decoupling indicator	functionality -> activates without reason	

Vehicle data

New GT/GTC and New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S3*	2021	E		*	*	*
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S3*	2024	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*
ZG2*	2020	E		*	*	*
ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*

Equipment combinations

PR numbers
with PR1

Documents

Document name
master.xml

Customer statement / workshop findings

Customer statement:

Bentley dynamic ride system fault warning displayed within the DIP

Workshop findings:

DTC P0B2600 (Hybrid Battery "A" Voltage High) with Symptom Code 28672

Technical background

Refer to the Measure section of this TPI

Production change

Not applicable

Measure

- 1) Refer to Rep.Gr 27 - Replace the Super capacitor
- 2) Once the work is complete - Raise a non technical DISS query confirming the issue is now resolved



NOTE: In the event that other DTC's are evident the operative should follow the applicable test plan, if necessary the operative should raise a DISS query and await feedback before conducting any further work

Warranty accounting instructions

Warranty Type 110 or 910

Damage Service Number 93 03

Damage Code 00 40

Labour

New Continental GT/GTC

Labour Operation Code 93 03 19 00

Time 50 TU

New Flying Spur

Labour Operation Code 93 03 19 00

Time 40 TU

Parts information

Refer to the ETKA parts catalogue