



Technical Service Bulletin

01 PSS MIL / EPC light on, various warnings or poor performance - P060C00 stored in ECM - V6 TFSI
01 23 95 2067767/6 November 17, 2023. Supersedes Technical Service Bulletin Group 01 number 23-56 dated April 17, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7, and Q8	2019 – 2022	All	Not Applicable
SQ7, SQ8, and RS Q8	2020 – 2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised header (Updated ECM code, Model Years)
5	04/17/2023	Revised header (Updated ECM code)
4	03/15/2023	Revised header (Updated Model years)

This bulletin only applies to Q7 MY 2020 – 2022 and Q8 MY 2019 – 2022.

Customer States:

- Various warning lamps are on in the instrument cluster (including MIL and/or EPC warning lamps).
- Poor performance.

Workshop Findings:

The following DTC is stored in the ECM, -J623- (address word 0001):

- **P060C00:** Control module internal system fault with symptom 30924.

Technical Background

There is a discrepancy in the engine control unit software.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service



Technical Service Bulletin

Please postpone repairs as there is currently no effective repair for the complaint described by the customer.

1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2023 (subject to change) and that no repairs are necessary at this point. This is a rare occurrence, but if it happens again, please explain to the customer that, an ignition cycle (i.e. shut off the vehicle and restart) after coming to rest will restore full vehicle and/ or engine performance. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2067767**) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.