

Audi On-car analysis list from November, 20 2023

Please contact Audi Helpline before attempting repair

All topics have associated worksheets to be filled out and attached to the TAC ticket. Worksheets can be found at: [Elsa2Go>>Service References>> Search v4p](#)

	Models	MY	Engine	Trans	Topic	Topic details
PT	Q3	2020-2021	All	All	Coolant warning Lamp	Customer states they receive a low coolant warning in the cluster. Coolant level appears to be full in the reservoir - Case does not relate to TSB 2061918 - Photo showing reservoir level
	A6, A7, Q7, Q8, S4, S5	2019-2023	3.0L	All	Catalytic Converter Inspection , P042000: Catalyst System,Bank1 Efficiency Below	- GFF Log with all fault codes and completed test plans. - Oil and Fuel samples (Hazmat containers can be requested through TAC). After oil sample have been collected, oil and filter should be changed. - VIN-4-Pin Worksheet with answers to questions
	All models with 3.0L engine (EA839)	2021-2023	3.0L (EA839)	All	Abnormal/no sound from engine sound generator	- Video/ sound recording of abnormal noise/ customer complaint from inside the vehicle before repair. - Video/ sound recording while running sound actuator test - Upload GFF log with executed test and relevant DTCs to GFF paperless - Video/ sound record of noise from inside the vehicle after repair.
	A4	2023	All	All	Coolant leak from expansion tank	Photo documentation of the source of the leak
	Q3	2019-2023	All	All	P008700 Low fuel pressure	- Applies to Q3 models within NVLW only - DTC P008700 - Attach completed worksheet on initial TAC contact.
	A6, A7, Q7, Q8, S4, S5	2020-2024	EA839 3.0L 2.9L	All	Parts Block Belt tension damper 06M903133AA	Only applicable if no prior repairs to Starter generator/ belt drive system performed. See worksheet
	Q4 e-tron	2022-2024	All	All	Charging cable cannot be removed from the vehicle	See e-tron charging questionnaire worksheet
	e-tron Q and SB Q8 e-tron and SB	2019-2024	All	All	Vehicle cannot be charged, charge socket lock without function	See e-tron charging questionnaire worksheet
	SQ5, Q7, Q8, S6, S7, S4, S5, RS5, A8	2021-2024	3.0 L and 2.9L Engines	All	EA839 Coolant Pump leaking	Coolant pump leaking Photo and video documentation See worksheet
EL	Q5	2021-2023	All	All	Q5 coolant reservoir cap broken	Tank and cap needed See worksheet
	A3	2023-2024	all	all	Wheel speed sensor Magnetic field too low	Cases needed with DTC: C101AF1;C101BF1;C101CF1;C101DF1 See worksheet
	e-tron GT	2022-2024	All	All	Front side window inoperative	Customer concern that a front door module function is inoperative water test, inspect door harness and pillar connection
BD	SQ5	2018-2024	All	All	Wire broke at air compressor V66	DTC P089200 Broken/Damaged/Loose connection found at V66 (Suspension Compressor) T3DL
	e-tron Quattro e-tron SB	2023-2024	Any	Any	Noise from Front Door Trim Panel	Noise from front door trim panel while driving - Video of noise before repair is performed - Photos of repair
	A5	2023-2024	Any	Any	Noise from Front Door speaker Grill	Noise from front door trim panel while driving - Video of noise before repair is performed - Photos of repair