



Preliminary Information

PIP5955 2024 Chevrolet Silverado GMC Sierra 6.6L (L5P) Duramax
DTC P0402, Rough Run at Idle and Surge

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500-3500	2024	All	All	6.6 L5P	All
GMC	Sierra 2500-3500	2024	All	All	6.6 L5P	All

Involved Region or Country:	North America
Condition:	1. DTC P0402. 2. Rough run at idle. 3. Stall when attempting to command the EGR position. 4. Surge or buck with light throttle and higher loads.
Cause:	This may be caused by a software anomaly.

Correction:

Please check for an ECM update.

If there are no updates available, refer to Service Information.

Version History

Version	1
Modified	11/29/2023 - Created on.



GENERAL MOTORS