



Bulletin No.: PIP5939  
Published date: 09/8/2023

# Preliminary Information

## PIP5939 SES Lamp With DTC P0315

Models

| Brand:    | Model:       | Model Years: | VIN: |     | Engine:  | Transmissions: |
|-----------|--------------|--------------|------|-----|----------|----------------|
|           |              |              | from | to  |          |                |
| Chevrolet | Corvette Z06 | 2023         | All  | All | 5.5L LT6 | All            |

|                            |                                                                                    |
|----------------------------|------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                      |
| Condition                  | Vehicle may have DTC P0315 setting erroneously with no other drivability symptoms. |
| Cause                      | ECM software                                                                       |

### Correction:

A software update is currently being developed to address this concern, this pertains to vehicles that have DTC P0315 set with no other drivability or DTC concerns.

Do not replace the ECM for this concern.

At this time it is recommended to perform a CKP sensor/relector variation learn and release the vehicle

This PI will be updated after the software update has been released.

### Version History

|          |                          |
|----------|--------------------------|
| Version  | 1                        |
| Modified | 09/08/2023 - Created on. |



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.