

GPOP - Issue Review System

Part Number: 68537555A\$, 68571964A\$

Part Description: Body Control Module

Issue For concern related to DTC U0140 - Lost Communication with Body Control Module,
Description: please follow published diagnostic information for this DTC to ensure all module connections are secure. Please check all the connections at BCM from other modules that could potentially report a loss of communication with the BCM and ensure that they are fully seated as per diagnostic information. Some affected modules may include :
HVAC;LBSS;RBSS;IPC;OCM;ICS;TBM;TCM;MSM;CSWM;ITBM;PCM;PTS/PAM;ESM;RFHUB;DSM;DTCM;IBS;AHLM;ABS;ORC;PLGM;DDM,DMFL;PDM;DMFR;EPS;ACC;FFCM;HVAC_R *Ensure to check all the wiring harness connected to BCM with Other Modules are proper. *Please disconnect the Battery Negative Cable for 15 minutes and then reconnect. *Clear the codes and check to see if any active DTC's return for U0140 *If still DTCs U0140 presents then contact Engineering Expert :
FCA REDACTED CONTENT.