



Technical Service Bulletin

20 Repair Authorization - N80 P04F000 Purge line performance

20 24 65 2069834/3 January 22, 2024. Supersedes Technical Service Bulletin Group 20 number 23-62 dated November 17, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, A5, A5 Cabriolet, and A5 Sportback	2021 - 2024	All	DMSA & DPAA Engine

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Header data</i> (Updated models)
2	11/18/2023	Revised <i>Service</i> (included additional information)
1	03/27/2023	Initial publication

Customer states:

- The MIL is illuminated.

Workshop findings:

The following DTC may be stored in the ECM, -J623- (address word 0001):

- P04F000:** EVAP system high pressure purge line performance.

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service



Technical Service Bulletin

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

- Verify the condition.
- Perform EVAP leak test per ELSA.
- Verify both ends of the vent pipe from the turbo to the breather are connected properly.
- If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the diagnostic log and leak test results to the TAC Web Ticket. If a leak is found please attach photos of the source of the leak to the TAC contact.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2069834**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.