



TECHNICAL SERVICE BULLETIN

2.7L EcoBoost - Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) P0456

24-2086

22 March
2024

Model:

Ford 2021-2023 Bronco	Engine: 2.7L EcoBoost
---------------------------------	-----------------------

Markets: Published By Ford North America

Issue: Some 2021-2023 Bronco vehicles equipped with a 2.7L EcoBoost engine may exhibit an illuminated MIL with DTC P0456 stored in the PCM. This may be due to the software level of the PCM and has no effect on vehicle operation. To correct this condition, perform the Service Procedure to reprogram the PCM to the latest software level using the FDRS scan tool.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2021-2023 Bronco
- 2.7L EcoBoost engine
- Illuminated MIL with DTC P0456 stored in the PCM

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2021-2023 Bronco 2.7L EcoBoost: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	242086A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

Service Procedure

1. Reprogram the PCM using the latest software level of the FDRS scan tool.

NOTE: Advise the customer this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.

The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.