

Technical product information

Topic	DTC B101C29 and/or DTC B101D29 evident within the airbag control unit (J234)
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2071047/4
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0015 - Airbag	B101C29: Driver seat belt switch implausible signal		Intermittent
0015 - Airbag	B101D29: Front passenger side safety belt switch implausible signal		Intermittent
0015 - Airbag	B101C29: Driver seat belt switch implausible signal		static
0015 - Airbag	B101D29: Front passenger side safety belt switch implausible signal		static

New customer code

Object of complaint	Complaint type	Position
occupant protection, pedestrian protection -> airbag	component / consumables	
occupant protection, pedestrian protection -> seat belts, 1st row	component / consumables	

Vehicle data

Bentayga Series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2021	E		*	*	*
4V1*	2022	E		*	*	*
4V1*	2023	E		*	*	*
4V1*	2024	E		*	*	*
ZV1*	2023	E		*	*	*
ZV1*	2024	E		*	*	*

Documents

Document name
master.xml

DTC B101C29 and/or DTC B101D29 evident within the airbag control unit (J234)

Customer statement / workshop findings

One or a combination of the following DTC's are evident within the airbag control unit (J234)

B101C29: Driver seat belt switch implausible signal

And/or

B101D29: Front passenger side safety belt switch implausible signal

Technical background

In the event the issue is as described the operative should refer to the Measure section of this TPI

Revision History - 2071047/4

The requirement to supply MWB data has now been removed from the Measure section

Production change

-

Measure

WARNING

Ensure all safety information and repair manual instructions within the repair manual are strictly adhered to when working on or around the air bag system and seat belt pre-tensioners as detailed within Rep.Gr 69

Referring to Rep.Gr 69 - Replace the applicable seatbelt buckle

Warranty accounting instructions

Time to replace x1 seatbelt buckle

Warranty Type 110 or 910

Damage Service Number 69 24

Damage Code 00 40

Time to replace x1 seatbelt buckle

Labour Operation Code 69 24 19 00

Time 70 TU

Diagnosis time

Labour Operation Code 01 50 00 00

Time As per ODIS must not exceed 10 TU

Parts information

Refer to the ETKA parts catalogue