



Technical Service Bulletin

01 PSS MIL on DTC P240700 Evap leak detection pump circuit

01 24 28 2066675/9 July 3, 2024. Supersedes Technical Service Bulletin Group 02 number 24-04 dated May 10, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3, RS 3, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q3, Q5, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, R8, R8 Spyder, TT, TTS, and TT Roadster	2022 -2023	All	Not Applicable
TT RS	2022		
Q8, SQ8, RS Q8, and R8 GT	2023		

Condition

REVISION HISTORY		
Revision	Date	Purpose
9	-	Revised <i>Service</i> (updated ETA) Updated <i>Warranty</i> (added table)
8	05/10/2024	Revised header (updated models)
7	04/04/2024	Revised header (updated models)

This bulletin only applies to Model Year 2022 and 2023 vehicles with gasoline engines.

Customer states:

- The MIL is illuminated.

Workshop findings:

The following DTC may be stored Passive/Static in the Engine control module, -J623- (address word 001):

- **DTC P240700** Evap emission control system leakage diagnosis pump current fluctuating

The event memory must not contain further relevant entries.

Technical Background



Technical Service Bulletin

Not applicable.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Delete **DTC P240700** and release the vehicle to the customer.
2. Explain to the customer that a solution is expected to be available by the end of the 3rd quarter of 2024 (subject to change) and no repairs are necessary at this point. Do not replace any components for this condition since it will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Access Audi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

For 2022 and 2023 Q5 PHEV, 2022 Q3 vehicles, as well as 2022 2.0l Q7 please refer to TSB 2071770: *01 MIL on, DTC P240700 Leak Detection Pump Current Fluctuating*.

Warranty

Claim Type:	• 110 Up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2048		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2066675/9		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information



Technical Service Bulletin

All parts and service references provided in this TSB (**2066675**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.