



Preliminary Information

PIP5976 DTC P2959

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500-3500	2024	All	All	6.6 L5P	All
GMC	Sierra 2500-3500	2024	All	All	6.6 L5P	All

Involved Region or Country:	North America, Israel, Palestine, Middle East
Additional RPO/s:	6.6 L5P
Condition:	Customer's concern may be of a Check Engine Light on.
Cause:	The dealer may find DTC P2959 set in the ECM.

Correction:

Engineering has found that this code may set early in the life of the vehicle if there is a potential for condensation to enter the valve and freeze.

If P2959 is the only code set, and there is a potential that this code set during freezing conditions and the valve operates as designed now, please do not replace the EGR bypass valve.

Engineering is working on a solution.

Version History

Version	1
Modified	05/02/2024 - Created on.

