



Preliminary Information

PIT6155A B19B0 Falsely Setting HUD Failure

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2024	All	All	All	All
Cadillac	CT5	2024	All	All	All	All
Chevrolet	Blazer EV	2024	All	All	All	All
Chevrolet	Silverado EV	2024 - 2025	All	All	All	All
GMC	Acadia	2024	All	All	All	All
GMC	Sierra EV	2024 - 2025	All	All	All	All

Involved Region or Country	North America
Condition	Code B19B0 SYM49 may be set in current or history.
Cause	B19B0 SYM49 may be falsely setting.

Correction:

1. Check that the HUD is operational.
 - a. If the HUD is operational, clear the B19B0 SYM49 and return vehicle to customer.
 - b. If the HUD is NOT operational, follow service information procedure for code B19B0 SYM49.

Note: A software fix will be available in the future to prevent this false setting code.

Version History

Version	2
Modified	04/24/2024 - Created on. 5/31/2024 - Updated models and model years.

