



Bulletin No.: PIT6155B
Published date: 06/26/2024

Preliminary Information

PIT6155B B19B0 Falsely Setting HUD Failure

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Envision	2024	All	All All	All
Buick	Enclave	2025	All	All All	All
Cadillac	CT5	2024	All	All All	All
Chevrolet	Blazer EV	2024	All	All All	All
Chevrolet	Silverado EV	2024 - 2025	All	All All	All
GMC	Acadia	2024	All	All All	All
GMC	Sierra EV	2024 - 2025	All	All All	All

Involved Region or Country	North America
Condition	Code B19B0 SYM49 may be set in current or history.
Cause	B19B0 SYM49 may be falsely setting.

Correction:

1. Check that the HUD is operational.
 - a. If the HUD is operational, clear the B19B0 SYM49 and return vehicle to customer.
 - b. If the HUD is NOT operational, follow service information procedure for code B19B0 SYM49.

Note: A software fix will be available in the future to prevent this false setting code.

Version History

Version	3
Modified	04/24/2024 - Created on. 05/31/2024 - Updated models and model years. 06/26/2024 - Updated model and model year.