

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Intermittent DTC CEM B124713 and CEM B124813		Ref. No. TJ 36944.1.0	
Issuer (Dept.) Technical Service		Issue Date 6/3/24	Status Date 6/25/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3552	
Function Description Side indicator lamp		Page Page 1 of 2	

DESCRIPTION:

If customer complains of intermittent DIM message stating “left turn signal malfunction” in combination with DTC CEM B124713 or CEM B124813 set, please follow advice under “Service”.

CEM = Central Electrical Module

DIM = Driver Information Module

CSC Customer Symptom Codes

Code	Description
CJ	Warning lights and chimes/Bulb failure indication/no indication

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
CEM	B124713	Intermittent
CEM	B124813	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2024-9999		-	202317-999952
225							2024-9999		-	202317-999952
227							2024-9999		-	202317-999952
234							2024-9999		-	202317-999952
235							2024-9999		-	202317-999952
236							2024-9999		-	202317-999952
238							2024-9999		-	202317-999952
246							2024-9999		-	202317-999952
256							2024-9999		-	202317-999952

Technical Journal 36944.1.0

SERVICE:

Please start by following this journal prior to any replacements:

- If the left rear turn indicator is not working, continue the fault tracing and repair according to our VIDA instructions.
- If the left rear turn indicator is working, through visual inspection and DTC stated above is set, do not replace any parts.

A software improvement is planned towards 2024 quarter 4.

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3552.