

Audi On-car analysis list from August, 22 2024

Please contact Audi Helpline before attempting repair

As of 6/7/2024 worksheets will no longer be used as a standard practice. Worksheets will only be required if listed in the topic details.

	Models	MY	Engine	Trans	Topic	Topic details
	Q5	2023-2024	DMSA	Any	ECM DTC P016900	Before performing work on the vehicle proceed as follows: 1. Verify DTC P016900 (Incorrect Fuel Composition) 2. Contact TAC for further instruction. Possible on-site needed.
	A3, Q3	2024	Any	Any	MIB3 – Stuck on loading user information when booting up	If the following criteria is met, contact TAC for possible data logger installation: - On bootup, the screen is stuck at the "loading user information" screen - User interaction is not possible during this time - Backup camera works normally
	Q4 e-tron	2022 - 2024	Any	Any	Roof panel buttons inop	Dome light buttons unresponsive or come on with no input Sunroof buttons are unresponsive (typically in addition to dome light) <u>See worksheet for instructions</u>
	Q7	2023-2024	Any	Any	Airbag light B12251B	If the DTC B12251B is stored in the airbag control module, J234 (da0015), contact TAC. Do Not perform GFF or test plans for this DTC. Do Not perform any repairs or disconnect the PODS sensor mat or PODS control module.
	A4, A4 allroad	2023-2024	Any	Any	front windows is noisy and/or binding	• Before making any repairs to the affected window, take a video of the customer's complaint. • After identifying the root cause (e.g. window regulator, window guide, etc.) take a video of the causal part causing the customer's complaint. • If the complaint was resolved (e.g. by cleaning the slot seals or reinstalling the window guide) take another video of the window operation.
	Q7	2023-2024	Any	Any	Front door wind noise	Wind noise from front door while at highway speeds Details findings needed for source of noise <u>See worksheet for further details</u>