



Bulletin No.: PIP5988
Published date: 07/16/2024

Preliminary Information

PIP5988 MIL Illuminated - DTCs P0089 and P2293

Models

Brand: Model: Model Years:			VIN: from to		Engine: Transmissions:
Chevrolet Silverado 2024			All	All LZ0	All
GMC Sierra 2024			All	All LZ0	All
Involved Region or Country:	North America, Europe, Kazakhstan, Uzbekistan, Middle East Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Columbia, Ecuador, Paraguay, Peru, Uruguay, Japan, Cadillac Korea, Philippines, Australia/New Zealand, Other Africa				
Condition:	Customer may complain of a MIL on the DIC.				
Cause:	P2293 and or P0089 set in the ECM.				

Correction:

Engineering is working on this issue and will have a bulletin released with a fix.

For now, if P2293 and/or P0089 are the only codes set and SI diagnostics point to High Pressure Diesel Fuel Injection Pump Replacement, do NOT replace the High Pressure Diesel Fuel Injection Pump.

Please replace the High Pressure Diesel Fuel Injection Rail.

Parts Information

Part Number	Description	Quantity
40009114	RAIL, HIGH PRESS DSL F/INJN	1

Additional SI Keywords

no, no-start, nostart, stall, start,

Version History

Version	1
Modified	07/11/2024 - Created on.

