



STAR ONLINE PUBLICATION



Case Number: S2408000093 Rev. A

Release Date: September 2024

Symptom/Vehicle Issue: High Voltage (HV) Battery Will not Take a Charge, Diagnostic Trouble Code B22A9-42-ECU Internal Performance-General Memory Failure Integrated Dual Charge (IDCM)

Customer Complaint /Technician Observation: The owner complains that they cannot charge the HV battery. The technician observed the IDCM is setting DTC B22A9-42-ECU Internal Performance-General Memory Failure Integrated Dual Charge (IDCM)

Discussion: If the vehicle has the above-described complaint; the DTC can be cleared allowing the vehicle to operate and charge as expected. The service update flash is available – see TSB 08-192-24. Do not replace any parts the replacement parts will perform the same.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.