



Service Bulletin

Bulletin No.: 24-NA-165

Date: August, 2024

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated - DTC P08ED Set

Brand:	Model:	Model Year:		Build Date:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette E-Ray	2024	2024	—	—	LT2	MLH

Involved Region or Country	North America, Europe, Middle East, Japan, Australia/New Zealand
Additional Options (RPOs)	HP1 (ELECTRIFIED PROPULS - ELECTRIC, ELECTRIC AXLE FRT, SPORT)
Condition	Some customers may comment on the MIL illuminated. Technicians may find DTC P08ED (Drive Motor Clutch Pawl Position Performance) set in the Drive Motor Control Module (DMCM) as current or history.
Cause	This condition may be caused by an issue with the Drive Motor Disconnect Clutch Switch.
Correction	Replace the Drive Motor Disconnect Clutch Switch.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Service Procedure

Refer to *Drive Motor Disconnect Clutch Actuator Replacement*.

Parts Information

Causal Part	Description	Part Number	Qty
X	SWITCH ASM- DRV MOT DIS- CONNECT CLUTCH	24053527	1
N/A	BOLT/SCREW - A/TRNS CASE CVR	11548404	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8630450	Drive Motor Disconnect Clutch Switch Replace- ment	Use Pub- lished Labor Operation Time

Version	1
Modified	Released August 15, 2024

