



SSM 53133 2022-2024 Mustang Mach-E - Inoperative BlueCruise And Lane Centering With DTC U3000:49 Stored In The CMR

Some 2022-2024 Mustang Mach-E vehicles may exhibit an inoperative BlueCruise and lane centering with diagnostic trouble code (DTC) U3000:49 stored in the camera module rear (CMR). This may be due to the software level of the CMR. Inform customers that engineering is currently working on a solution for this condition and will be released via a software update delivered over-the-air (OTA) expected in 1Q of 2025. Software will update automatically if vehicle connectivity is enabled in the vehicle's settings. Schedule a service visit for customers who have disabled vehicle connectivity or who report that they did not receive the update in 1Q of 2025. Monitor OASIS for additional information.