



TECHNICAL SERVICE BULLETIN

6.7L - Illuminated MIL With DTC P20A5 - Built On Or Before 03-Oct-2024

24-237913 November
2024**Model:**

Ford 2024 F-Super Duty	Built on or before 03-Oct-2024
----------------------------------	--------------------------------

Markets: North American markets only

Issue: Some 2024 F-Super Duty vehicles built on or before 03-Oct-2024 and equipped with a 6.7L engine may exhibit an illuminated MIL with DTC P20A5 stored in the PCM. This may be due to the software in the glow dosing module (GDM) and does not affect vehicle operation. Due to OBD functionality, the GDM may be referred to as the SOBDMC in the FDRS scan tool. To correct the condition, follow the Service Procedure to reprogram the SOBDMC using the latest software level of the FDRS scan tool.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2024 F-Super Duty
- Built on or before 03-Oct-2024
- 6.7L diesel engine
- Illuminated MIL with DTC P20A5 stored in the PCM

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2024 F-Super Duty 6.7L: Retrieve DTCs And Reprogram The SOBDMC (Do Not Use With Any Other Labor Operations)	242379A	0.4 Hrs.

Repair/Claim Coding

Causal Part:	12B533
Condition Code:	04

Service Procedure

1. Reprogram the SOBDMC using the latest software level of the FDRS scan tool.
2. If DTCs P208D, P20FC, P20FD, P20E8, P20FA and/or P249D were present in the PCM in addition to P20A5, refer to WSM, Section 303-08 for normal diagnostics.

© 2024 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.