



Bulletin No.: PIT6068D
Published date: 11/1/2024

Preliminary Information

PIT6068D Service Driver Assist B1A05 Symptom 54

Models

Brand:	Model:	Model Years:	VIN: from to		Engine:	Transmissions:
Cadillac	LYRIQ	2024 - 2025	All	All	All	All
Chevrolet	Blazer EV	2024 - 2025	All	All	All	All

Involved Region or Country	North America
Condition	Service driver assist message. On inspection B1A05 symptom byte 54 will be found in the B174W Front View Camera Module (FVCM).
Cause	Software

Correction:

Reprogram B174W FVCM using SPS if new software is available.
After programming perform the Front View Camera -Windshield Learn procedure as found in SI.
If B1A05 is not accompanied with symptom byte 54 follow diagnostics in SI for this code.

Version History

Version	5
Modified	10/03/2023 - Created on. 10/04/2023 - Removed statement to learn FVC after programming. 10/14/2024- Updated models. 10/25/2024- Added statement to perform FVCM learn after reprogramming to the correction. 11/01/2024- Added symptom byte 54 to title and correction.