



Technical Service Bulletin

90 Driver Assist systems DTC B187A00: Park steer assist cancelation (symptom number 98341)

90 24 46 2072566/2 November 20, 2024. Supersedes Technical Service Bulletin Group 90 number 23-66 dated December 22, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 allroad, S6, RS 6Avant, A7, S7, RS 7, A8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2021 – 2025	All	Driver Assist Systems
e-tron, and e-tron Sportback	2021 -2023		
A7 e quattro	2021 – 2022		
A8 e quattro	2021		
e-tron GT, and RS e-tron GT	2022 – 2025		
Q8 e-tron, Q8 Sportback e-tron, SQ8 Sportback e-tron, and SQ8 Sportback e-tron	2024 – 2025		

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added MY25, updated customer codes)
1	12/22/2023	Initial publication

Customer states:

- No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

The following DTC or DTCs and symptom code(s) may be stored in the Driver Assistance Systems control module -J1121-, (address word 00A5):

- DTC B187A00:** Cancel parallel parking assist (**Symptom number 98341**).



Technical Service Bulletin

Technical Background 1

This DTC is an unauthorized / ghost fault that is entered during vehicle startup and immediately becomes passive as soon as the control module initialization is complete.

Production Solution

Not applicable.

Service

The DTC is an unauthorized / ghost fault and does **not** lead to a restricted function or a message in the instrument cluster. Any claims for repairs based on this DTC may be denied by warranty.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2072566**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.