



Technical Service Bulletin

96 Driver assist systems: various camera-based driver assist systems unavailable (DTC B200FF2 (1123875))

96 24 06 2075891/1 November 7, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5 Sportback, S5 Sportback, RS 5 Sportback, Q5, Q5 e quattro, Q5 Sportback, SQ5, and SQ5 Sportback	2021 – 2025	All	Camera for Driver Assist System
A5, A5 Cabriolet, S5, S5 Cabriolet, and RS 5	2021 - 2024		

Condition

Customer states:

Various camera-based driver assist systems are sporadically unavailable. One or more of the following messages are displayed on the instrument cluster:

- Audi pre sense: fault.
- Traffic sign recognition: fault.
- ACC with traffic jam assist: unavailable.
- Audi active lane assist: currently unavailable.
- Depending on the driving situation, the vehicle heals itself after a short amount of time, or an ignition cycle may be required.

Workshop findings:

The following DTC and symptom code is stored sporadically in *Front Camera for Driver Assist Systems - R242-*, (address word 00A5):

- **DTC B200FF2:** Internal malfunction (symptom code 1123875).



Technical Service Bulletin

Technical Background 1

Not applicable.

Production Solution

Not applicable.

Service

Please clear the **DTC B200FF2**: Internal malfunction (symptom code 1123875) with ODIS.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9638		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
	GFF / Guided Functions	0150 0010	See SRT with associated operations
Claim Comment:	As per TSB 2075891/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



CAUTION

Do not replace any parts. Replacing parts will not remedy the customer complaint. Unnecessarily replaced parts or labor will be denied under warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2075891**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.