



Bulletin No.: PIP6020A
Published date: 10/29/2024

Preliminary Information

PIP6020A DTC P244B

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet Silverado	2500HD - 3500HD	2024 - 2025	All	All 6.6 L5P	All
GMC	Sierra 2500HD - 3500HD	2024 - 2025	All	All 6.6 L5P	All

Involved Region or Country:	North America, Israel, Palestine, Middle East
Condition:	A customer may comment about a check engine light on. A dealer technician may find DTC P244B set in the ECM.

Correction:

Engineering has found that this code may set if the vehicle was recently washed, and/or water collected in the Differential Pressure Sensor (DPS).

If the vehicle undercarriage was recently exposed to water, wait overnight for the water to dry.

If the vehicle still sets the code, refer to SI.

If the vehicle does not reset the code, engineering is aware of the issue and is working on a solution.

This PI will be canceled, and a bulletin will be released when a fix is available.

Version History

Version	2
Modified	10/25/2024 - Created on. 10/29/204 - Updated Model Year.



GM Global Brands
© 2024 General Motors. All Rights Reserved.