



Bulletin No.: PIT5696H
Published date: 12/5/2024

Preliminary Information

PIT5696H Diagnostic Aid : ABS/TCS MIL On Code C0010 Symptom 5A Stored

Models

Brand:	Model:	Model Years:	VIN: from to		Engine:	Transmissions:
Buick	Envision	2018 - 2022	All	All	All	All
Cadillac	SRX	2010 - 2016	All	All	All	All
Chevrolet	Colorado	2018 - 2022	All	All	All	All
Chevrolet	Equinox	2015 - 2024	All	All	All	All
GMC	Canyon	2018 - 2022	All	All	All	All
GMC	Terrain	2015 - 2024	All	All	All	All

Involved Region or Country:	North America
Condition:	ABS / TCS MIL on, Code C0010.5A stored in EBCM. Possible OnStar notification.
Cause:	There currently have been no cases of a functional concern regarding this code so if the C0010.5A is stored alone, clear the code and road test. If the C0010.5A is stored with other communication or component codes diagnose those codes. See note below.

Note: If the code C0010.5A is the only code stored clear the code and road test, advise the customer that this code can be caused in a 3 point turn kind of maneuver. If the vehicle is still moving forward and the shifter moved to reverse this code can be stored. Have them make sure they come to a complete stop before shifting.

Version History

Version	9
Modified	06/28/2019 - Created on 08/22/2019- Updated Title 12/11/2019 - Added 2020 MY and added text. 01/09/2020 - Added 2015-17 Equinox / Terrain. 03/17/2020 - Added 2010-2016 SRX. 03/16/2021 -Added 2021 MY for Colorado/ Canyon and Equinox/ Terrain. 04/11/2022 - Added 2022 Model Year. 08/15/2022 - Added 2022 Envision. 12/05/2024 - Added 2023 and 2024 MY for Equinox/Terrain.