

Uncontrolled Copy

ID # CBR-2412

Version 1

Title

Volvo Chassis - VN (4) - TMPS fault U3000-05

Abstract

This CBR solution informs technicians that the U3000-05 System Programming Failure DTC following software updates has no permanent solution currently available

Content

Published 16 December 2024

Valid For

Volvo Chassis - VN(4)

Model Year - 2025

Current Status

Currently, there is no permanent solution available for resolving the U3000-05 System Programming Failure DTC, which occurs after software updates. The Instrument Cluster (IC) message associated with the DTC can be disregarded, as it does not affect vehicle operation.

Additional Guidance

- If the IC message (please show the graphic of the IC message), or if Techtool DTC readout shows U3000-05, please disregard the DTC, and take no repair action until the CBR is updated to communicate the availability of a permanent solution.
- Please do not replace hardware associated with this fault, as it will not resolve the DTC.

Future Updates

When a permanent solution has been validated, this CBR solution will be updated accordingly.

Tags

volvo

vn4

u3000-05

vn 4

Categories

Make and Model > Volvo > All-New VNL

 Live UI

