



Technical Service Bulletin

00 Diagnosis: Ghost DTC U183A00 in diagnostic address 8125

00 24 00 2076151/1 December 2, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5, S5, Q6 e-tron, and SQ6 e-tron	2025	All	Not Applicable

Condition

Customer states:

- There is no customer complaint regarding the HUD.

Workshop findings:

The following DTC and symptom code is stored in *the Application Service 3 System 1 Infotainment (HCP3) - SWC6-*, (address word 8125):

- DTC U183A00:** Head-up display control module, checksum faulty (symptom code **2031620**).

However, there is no malfunction. The head-up display image is present, and no issues can be found.

Technical Background 1

The specified event memory entry may appear due to a software issue although there is no malfunction in the head-up display.

Production Solution

In vehicles built starting from week 48/25 onwards, the specified event memory entry will reliably indicate a functional issue with the head-up display.

Service

Please note the information shown in ODIS S regarding the specified DTC.

Do not perform any repairs. Any repairs for this concern may be denied.



NOTICE

The DTC codes listed above do not require a TAC ticket for repair authorization reporting.



Technical Service Bulletin



NOTICE

If there is a customer complaint, this TSB does not apply, and the vehicle must be repaired following Guided Fault Finding.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2076151**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.