



SSM 53293 2024-2025 Escape - 1.5L EcoBoost - Illuminated MIL With DTCs P0300 And P0316

Some 2024-2025 Escape vehicles equipped with a 1.5L EcoBoost engine may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble codes (DTCs) P0300 and P0316 stored in the powertrain control module (PCM). This concern typically happens after initial engine start up following an overnight cold soak. This may be due to the software in the PCM and replacement or reprogramming of the PCM will not resolve this condition. This condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected in Q1 2025. Monitor Professional Technician System (PTS) for additional information and schedule service appointments for customers once the repair becomes available.