



Bulletin No.: PIT6319
Published date: 01/15/2025

Preliminary Information

PIT6319 Service High Voltage Message and No Heat

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2025	All	All	All	All
Cadillac	OPTIQ	2025	All	All	All	All
Chevrolet	Blazer EV	2025	All	All	All	All
Chevrolet	Equinox EV	2025	All	All	All	All

Involved Region or Country	North America
Condition	Service high voltage message. Heat begins to blow cold. P1C01 set in history. Any or all of these symptoms may be found.
Cause	Software

Correction:

If P1C01 is in history do not attempt any repairs at this time.
Advise the customer that shutting the vehicle down and restarting should temporarily alleviate the concern.
It may take a few key cycles for the code to clear and the MIL to turn off.
Advise the customer that engineering is working on updated software to permanently resolve this issue.
A bulletin will be released when software is available.
If P1C01 is set current or the customer states that the concern has occurred multiple times, diagnose the vehicle following SI.

Version History

Version	1
Modified	01/15/2025 - Created on.

