SSM 53473 2025 F-150 Lightning - DTC B1717:06 Setting In The HPVCM When A Diagnostic Self-Test Is Performed

Some 2025 F-150 Lightning vehicles may set diagnostic trouble code (DTC) B1717:06 in the heat pump valve control module (HPVCM) after a diagnostic self-test is performed. If DTC B1717:06 is present in the history status, and no customer symptoms are present, it has no effect on functionality or durability of vehicle and can be cleared. Replacement or reprogramming of the HPVCM will not resolve this condition. Disregard DTC B1717:06 if no other DTCs are present in the HPVCM, no warning indicators are illuminated while the vehicle is on, and no additional symptoms are present. If other DTCs or observable symptoms are present, refer to Workshop Manual (WSM), Section 412-00 for additional diagnosis and testing.