Technical Service Bulletin

01 DTC P195000 (V7- cooling fan stiff/blocked) stored in engine control

01 17 12 2047707/1 May 5, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2013 – 2015	All	Not Applicable
A6, A7	2011 – 2015	All	Not Applicable
A5, A5 cabriolet	2010 – 2015	All	Not Applicable
Q3	2012 -2015	All	Not Applicable
Q5	2011 - 2015	All	Not Applicable

Condition

Customer concern:

- Not applicable

Workshop Findings:

- The DTC P195000 is often noticed during a service repair or other repairs which are not related to the cooling fan

Technical Background

During activation of the cooling fan under certain conditions for example; driving at higher speeds. The following DTC can be entered into the engine control module (ECM), J623 (address word 0001):

- **DTC P195000** (cooling fan -V7 - stiff/blocked)

Tip: This DTC does not effect on the function of the cooling fan and does not indicate a failure in the cooling fan.

Production Solution

Not applicable.

Service

If this DTC is discovered during service or any other unrelated repair, erase the DTC upon exiting GFF.

© 2017 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

When diagnosing this DTC due to a customer concern, only replace the cooling fan if the GFF test result instructs to replace the cooling fan.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2047707) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2017 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.