Bulletin No.: PIT5607A
Published date: 02/9/2018

Preliminary Information

PIT5607A Service Engine Soon MIL on P050F Stored

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Terrain	2018	All	All	All	All
Chevrolet	Equinox	2018	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	None
Condition:	Intermittent SES MIL On , DTC P050F Stored
Cause:	Engineering is investigating this concern.

Correction:

Engineering is currently investigating this concern.

Service Procedure:

Test the brake vacuum system to verify no leaks present and verify brake operation performance. If leak identified follow SI diagnostics. If no leak identified clear codes and return the vehicle to the customer. GM is investigating root cause for DTC setting with no system leak present.

Warranty Information

Labor Operation:	Description:	Labor Time:
2480358	Inspect For Vacuum Leak and Clear DTC's	0.3

Version History

Version	2
	02/09/2018 Updated Service Procedure Verbiage.

© 2016 General Motors. All Rights Reserved.