Bulletin No.: PIP5515A
Published date: 03/14/2018

Preliminary Information

PIP5515A Repeat MIL On P2097

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016	All	All	1.5L L3A	All

Involved Region or Country	**North America**
Condition	**Repeat MIL On P2097**
Cause	**Under Investigation At This Time.**

Correction:
Some customers may comment that the MIL has come on.
DTC P2097 may be set current or in history.
Confirm that the latest calibrations from 17058 have been installed.

If the calibrations are current, perform the diagnostic in Service Information for the code.

If the diagnostic for the code fails to isolate the cause of the concern, do not attempt repairs at this time.

Clear codes and return the vehicle to the customer.

Advise the customer that GM is aware of this concern and is working on a resolution.

Version History

Version	**2**
	3/12/2018 Updated Model Years and Correction

© 2016 General Motors. All Rights Reserved.