Service Bulletin

Bulletin No.: PIP6135

Date: September, 2026

PRELIMINARY INFORMATION

Subject: SES Lamp with DTC P00C6 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2027		ALL	ALL	6.7L LS6	ALL

Involved Region or Country	North America
Condition	DTC P00C6 (Fuel Rail Pressure Low During Engine Cranking) set in history.
Cause	Engineering is currently investigating.

Correction

If DTC P00C6 is set in history, clear the DTC and start after an overnight cold soak, if the DTC does not return the vehicle can be released.

If the DTC is active or returns when starting after an overnight cold soak, perform the following: Follow SI diagnostics for DTC P00C6.

Record GDS2 session logs of high and low side fuel system data under conditions for running DTC P00C6.

Start a Technical Assistance Case and provide data/findings related to SI diagnostics.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the appropriate warranty labor operation based on the actual cause and repair. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Version	1
Modified	09/28/2026 Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

Copyright 2026 General Motors. All Rights Reserved.