VOLVO CAR
SERVICE AND PARTS BUSINESS

Technical Journal

TITLE:

Alarm Service Required message in DIM, CEM DTC

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:	
TJ 30588	Technical Service	United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-05-12	STATUS DATE: 2016-05-16
FUNC GROUP: 3669	FUNC DESC: Miscellaneous	Page 1 of 2	

"Right first time in Time"

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2016		0000001-0095355	201505-201616

CSC Customer Symptom Codes

Code	Description
KH	Alarm/False alarm
XM	Alarm/Other alarm problems
7G	Text window and warning symbol/Yellow symbol and text message
FB	Text window and warning symbol/Other problems

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
CEM	U132A96	Intermittent

Rows beginning with * are modified
Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste.
© 2016 VOLVO CAR USA, LLC

Text

DESCRIPTION:
If Alarm Service Required message is shown in the DIM and DTC CEM-U132A96 is present, follow advice under Service.

SERVICE:
Perform Total Upgrade XC90 (Software Product 31483292).
If the DTC returns with the latest SW, replace the BBS (Battery Backed Sounder).

VEHICLE REPORT:
Not applicable.

CEM = Central Electronic Module
DIM = Driver Information Module