Bulletin No.: PIP5473
Published date: N/A

Preliminary Information

PIP5473 2017 9T50 M3E MIL Setting DTC P0721, P0722, P0723, P0716, P0717, P176B, P176C, Or P176D Current Or History

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2017	All	All	LTG	M3E

Involved Region or Country	**North America**
Additional Options (RPO)	**M3E**
Condition	**Intermittent or current DTCs P0721, P0722, P0723, P0716, P0717, P176B, P176C, or P176D setting illuminating the Service Engine Soon light on.** **DTCs may be current or in history.**
Cause	**Follow published SI information for any DTC(s) that are found.**

Correction:
If root cause for a DTC has not been found through appropriate SI diagnostics, then replace the speed sensor related to the DTC.

Version History

Version	**1**
Modified	

©2016 General Motors. All Rights Reserved.