**Bulletin No.:** PIP5389D
**Published date:** 04/10/2017

# Preliminary Information

## PIP5389D SES Lamp With DTC P015A

## Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|---|---|---|---|---|---|---|
| | | | from | to | | |
| Chevrolet | Equinox | 2013 - 2017 | All | All | 2.4L LEA | All |
| GMC | Terrain | 2013 - 2017 | All | All | 2.4L LEA | All |

## Supersession Statement

This PI was superseded to update Recommendations / Instructions. Please discard PIP5389C.

**The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.**

## Condition / Concern

**A customer may comment on an SES light with DTC P015A set.**

## Recommendations / Instructions

**A repair for this condition has been established, refer to Technical Service Bulletin 17-NA-086 for repair information.**
**Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.**

©2016 General Motors. All Rights Reserved.