Bulletin No.: PIP5447B
Published date: 04/14/2017

Preliminary Information

PIP5447B P3400 setting with 8 speed only

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2016 - 2017	All	All	6.2L LT1	8 Speed
Chevrolet	Corvette	2016 - 2017	All	All	6.2L LT1	8 Speed

Involved Region or Country	North America
Additional Options (RPO)	N/A
Condition	The vehicles listed in the PI may have a concern of a DTC P3400 setting
Cause	Unknown at this time

Correction:

Follow SI diagnostics for DTC P3400 to be sure this is not a false concern.
Document the findings and repair as needed per the service procedure.
Try to capture a GDS2 session for review.
If the concern was not duplicated or repaired following SI, call GM Technical Assistance to set up a case and provide results from SI diagnostics.

Warranty Information

Labor Operation	Description	Labor Time
4029929	Engine Malfunction Indicator Lamp (MIL) Active - Customer Concern Not Duplicated	Use Published Labor Operation Time

Version History

Version	3
Modified	12/12/2016 Updated to add Models
	04/04/2017 Updated Correction Field

©2016 General Motors. All Rights Reserved.