Next Unread Message

View Message

Sent on 01 05 2015 **Expires on** 01 19 2015

From Parts and Service Division

Subject Request for Parts: 2014 Accord Hybrid MIL On with DTC P0134 Stored

To: All Honda Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2014 Accord Hybrid MIL On with DTC P0134 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2014 Accord Hybrid with a complaint of the Malfunction Indicator Lamp (MIL) on with P0134 (Air Fuel Ratio Sensor [Bank 1, Sensor 1] Heater System Malfunction) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to your attempting any repair.

Qualifier

AHM is interested ONLY if the vehicle meets the following requirement:

1. DTC P0134 must be stored.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.