Technical product information

Topic	HVAC Diagnostic Trouble Code U132900
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2048536/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0008 - Air Conditioning	U132900: Sunlight photo sensor implausible message		Intermittent

New customer code

Object of complaint	Complaint type	Position
air conditioning -> operation, air conditioning control -> solar radiation sensor	component / consumables -> damaged	

New workshop code

Object of complaint	Complaint type	Position
air conditioning -> operation, air conditioning control -> solar radiation sensor	functionality -> without function / defect	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*
4V1*	2018	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Customer may not be aware of Diagnostic Trouble Code (DTC) / Workshop may discover code whilst running a DTC log as part of other investigations on the car

Technical background

The Sunlight photo sensor code is to be considered spurious in relation to faults or reports such as *'no AC function'* or *'blowing warm air'*

Production change

.

Measure

The following may be seen during routine interrogation of vehicle system do not take any investigative action in response to the following fault code unless there is an actual fault evident in the system or a fault symptom has been reported by the owner. **Note:** In the case of solar sensor failure or if the following spurious DTC is stored this should not affect the cooling performance of the HVAC system

U132900 – Sunlight photo sensor implausible message

Passive/sporadic

393490

00001000