Technical Service Bulletin

PSS 20 MIL on; (DTC P046100 - Fuel level sensor, circuit range/performance)

20 16 59 2041594/6 January 25, 2016. Supersedes Technical Service Bulletin Group 20 number 15-58 dated December 8, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet, A6, A7, A8	2014 - 2016	All	Not Applicable

Condition

REVISION HISTORY		
Revision	**Date**	**Purpose**
6	-	Revised header data (Added model code)
5	12/8/2015	Revised header data (Corrected Elsa display error)
4	11/19/2015	Revised *Warranty* (Added Warranty table)

- MIL on.
- **DTC P046100** (Fuel level sensor, circuit range/performance) is stored in the engine control module (ECM), J623 (address word 01).

When:	Normal driving conditions, city or highway.
Speed:	Any speed
Temperature:	Not applicable
DTC:	P046100

Technical Background

Not applicable.

Production Solution

Not applicable.

© 2016 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Service

1. Explain to the customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern. Clear the DTC and release the vehicle.
2. Create a PSS record in the PSS application via the Pending Service Solutions link in AccessAudi (under *Related Links>>Service*), or through the Technical Assistance page in Elsa.

Warranty

Claim Type:	1EB		
Service Number:	DADP		
Damage Code:	0010		
Diagnostic Time:	Check and clear fault	0132 0000	20 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion. (Refer to Section 2.2 of the Audi Warranty Policies and Procedures Manual and Audi Warranty Online/Resource Center for DADP allowance details.)		
Claim Comment:	As per PSS TSB #2041594/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2041594) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2016 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.