GM CUSTOMER CARE AND AFTERSALES
DCS4198
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 20, 2016

Subject: Service Update Bulletin - 33110
8-Speed Transmission Turbine Shaft Failure
Programming Temporarily Suspended

Models: 2016 Chevrolet Camaro
Equipped with 3.6L V-6 and 8-Speed Transmission (LGX/M5T)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Manager, and Warranty Administrator

This message is to inform dealers that Service Update Bulletin 33110, released on September 16, 2016 through GM Global Connect Message GCUS-3-696, is being temporarily suspended. This action is necessary due to an anomaly in the software that may result in possible Diagnostic Trouble Codes being set once the reprogramming event is complete. The affected calibration has been disabled and will not be available until further testing has been completed.

Involved vehicle status in IVH will be temporarially changed from “open” to “released in error” until the calibration has been reinstated. Dealers will be notified when programming can be resumed. We apologize for any confusion this situation may cause.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES