Bulletin No.: PIP5467A
Published date: 10/4/2017

Preliminary Information

PIP5467A Repeat Codes P2096 and P2098

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2014 - 2017	All	All	6.2L LT1	M5U

Involved Region or Country	North America
Condition	Customers may experience MIL Illumination with a repeat diagnostic codes P2096 P2098. These code can be set when the operator drives in a digital manner when they tap the accelerator pedal (on - off - on -off) to maintain speed.
Cause	Normal vehicle operating characteristic

Correction:

Engineering aware of the issue, at this time this is considered a normal vehicle operating characteristic.

Warranty Information

Labor Operation	Description	Labor Time
4081528*	Retrieve and Clear ECM Codes P2096 and P2098	0.3 hr
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	10/04/2017 to update correction

© 2016 General Motors. All Rights Reserved.