Bulletin No.: PIP5447C
Published date: 10/24/2017

Preliminary Information

PIP5447C P3400 setting with 8 speed only

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2016 - 2017	All	All	6.2L LT1	8 Speed
Chevrolet	Corvette	2016 - 2017	All	All	6.2L LT1	8 Speed

Involved Region or Country	North America
Additional Options (RPO)	N/A
Condition	The vehicles listed in the PI may have a concern of a DTC P3400 setting
Cause	Unknown at this time

Correction:

Follow SI diagnostics for DTC P3400 to be sure this is not a false concern.
Drive the vehicle and see if the AFM is switching without any concern. If switches normal replace the ECM.
Document the findings and repair as needed per the service procedure.
Try to capture a GDS2 session for review.
If the concern was not duplicated or repaired following SI, call GM Technical Assistance to set up a case and provide results from SI diagnostics.

Warranty Information

Labor Operation	Description	Labor Time
4029929	Engine Malfunction Indicator Lamp (MIL) Active - Customer Concern Not Duplicated	Use Published Labor Operation Time

Version History

Version	4
Modified	12/12/2016 Updated to add Models
	04/04/2017 Updated Correction Field
	10/24/2017 Updated repair information

© 2016 General Motors. All Rights Reserved.